Approved For Release 2001/08/13 : CIA-RDP78105439A000400050028-6 NOFORN Copy No. 25

CONTINUED CONTROL

ANDUM

COMPT

PHOTOGRAPHIC INTELLIGENCE MEMORANDUM DECLASS REVIEW by NIMA/DOD

KIOUSIN DOCKS, SHANGHAL, CHINA

S-13621:



GP/I - 197

16 July 1956

CENTRAL INTELLIGENCE AGENCY

OFFICE OF RESEARCH AND REPORTS

CONTINUED CONTROL

NOFORN

SCORE

S-E-C-R-E-T NOFORM C-NTINUED CONTROL

PHOTOGRAPHIC INTELLIGENCE MEMORANDUM

KIOUSIN DOCKS, SHANGHAI, CHINA

This report presents the results of photo analysis of the area known as KIOUSIN DOCKS, Shanghai, China (32°12°15"N-121°29'30"E).

25X1D

The analysis is based on photographic missions exposed in

25X1D

The Kiousin Docks, Shanghai are located on the West bank of the Huang-P'u-Chiang between the Sun Dah Flour Mill to the south and the Tung Chang Cotton and Oil Mill to the north. The yard is approx-imately 500 feet wide and 600 feet in depth. For additional detail see map, Annex 1 to this report.

Buildings and other installations as shown on the attached map, purposes and their sizes are as follows:

| Item No. | Purpose | | | Size(in feet) | |
|----------|---------|----|----|---------------|-------|
| 1 | Offices | | | X 275 | 25X1D |
| 2 | Shops | | | | 25X1D |
| 3 | Storage | | | X 115 | 25X1D |
| 4 | Shops | | | | 25X1D |
| 5 | Shops | t) | • | | 25X1D |
| 6 | Shops | | 37 | 70 X | 25X1D |

S-E-C-R-E-T NOFORN (CONTINUED CONTROL

S-E-C-R-E-T NOFORM CONTINUED CONTROL

| | Itam No. | Purpose | Size(in feet) | | | |
|-------|--|--------------------------------------|------------------|----------|--|--|
| | 7 | Graving dock | 270 long 35 ent | ranc e | | |
| | 8 . | Probable construction of new gra | aving dock | | | |
| | 9 | Marine railway | | | | |
| | • 10 | Possible new graving dock under | construction | | | |
| | The dock yard shows considerable development during the period | | | | | |
| 25X1D | | There has been litt. | le apparent con- | 1 2** | | |
| | struction of ne | sw buildings but the | indicates a | | | |
| | considerable ex | manion of vessel handling facilities | 5. | 25X1D | | |

Two small marine railways have been replaced with a single marine railway (item No. 9) that is capable of handling vessels at least 190 feet long. A second graving dock (item No. 8) is under construction in an area formerly occupied by two small marine railways. Completed length of this dock will be approximately 250 feet.

A third graving dock may be under construction as indicated at Item No. 10 on the Annex to this report.

A minor but significant change is to be noted in the yard. The period between the photo missions has seen areas of the yard take on an appearance of order and cleanliness that was notably lacking

> S-E-C-R-E-T NOFORM CONTINUED CONTROL

S-R-C-R-E-T HOFORM
CONTINUED CONTROL

25X1D

25X1D

25X1D

There were ten vessels tied to the dock area ______ These included seven identical ______ possibly patrol craft, two ______ cargo vessels and one 90 by 25 foot vessel.

25X1D

In addition there were 190 foot vessel on the marine railway (item No. 8) and three floating gantry cranes with hull dimensions of 80 by 30 feet in the existing graving dock.

o

S-E-C-R-E-T ... NOPORN CONTINUED CONTROL

13

3

